



IC Verify Set-up Instructions for Cherry 7000/8000 Keyboards

- 1) Go to system prompt or editor (Notepad or a DOS prompt)
- 2) Press and hold the following six keys (left and right) to enter program mode:

Ctrl + **Alt** + **↑ Shift** (left and right)

3) Press **J** , **! 1** , **Y**

4) Press **J** , **@ 2** , **Y**

5) Press **V** , **% 5** , **↑ Shift** + **% 5** , **Enter** (in the Num Pad Section)

6) Press **V** , **^ 6** , **:** , **Enter** (in the Num Pad Section)

7) Press **W** , **% 5** , **↑ Shift** + **? /** (in the QWERTY section) , **← Enter** , **Enter** (in the Num Pad Section)

8) Press **W** , **^ 6** , **↑ Shift** + **? /** (in the QWERTY section) , **← Enter** , **Enter** (in the Num Pad Section)

9) Press the space bar to exit program mode